
Shuttle

Shuttle

All stainless steel, cantilever and bottom side support.

Three-dimensional coordinate movement, with a photoelectric sensor, with automatic identification of the station function, the use of programmable logic control system, touch screen human-computer interface display, system menu and connection press and drying operation selection procedures.

Display the alarm and fault information display function

Product link : <https://www.hoop86.com/?p=1102>